

BL0003 Controller Firmware Update

Installing the update tool

1. Extract the update files

Extract the contents of "BL0003 - Update Tool & Firmware.zip" before installing the update tool.

2. Install the update tool

Open the update tool folder.

 Media Product Tool V2.10.05


3. Run the installer

Open the setup.exe file.




4. Complete the installation

Follow the setup wizard instructions to complete the installation.



5. Find the desktop shortcut

The Multimedia Product Tool icon will appear on your desktop, as shown in the image.




BL0003 Controller Firmware Update

Program setup and firmware selection

6. Configure the update options

Open Multimedia Product Tool and select the firmware programming, automatic restart and automated production options. In the screenshot, these are PRODUCTION, RESTART and AUTOMATION, respectively.




7. Select the firmware file

Click the button shown below (Replace Firmware):



When the file selection window opens, click CHOOSE, open the firmware folder, select MAB1538_PS5_5005B_V1.36_260918.fw and click Open.



BL0003 Controller Firmware Update

Connecting the controller and updating

8. Connect and update the controller

Connect the USB-C end of the cable to the controller. Press and hold the triangle button shown in the image and, while holding it, connect the USB-A end to your computer. Then release the button.



The update will start automatically and take approximately 2-3 seconds.

The update is complete when the progress reaches 100%. The controller will restart.

If the controller becomes unresponsive during the process, press the RESET button on the back.

9. Update another controller

To update another controller, repeat step 8.